

I'm not a robot



























Heat treatment is a metallurgical process that involves changing a material's physical properties. It is also said to be a way in which the physical mechanical properties of a metal are changed by heating and cooling methods without changing the shape of the working metal. You should also learn about Annealing with this detailed guide! Theory of Heat Treatment Heat treatment can differ depending on the metal/material, but there are three main differences in the process: the heating temperature, the cooling rates, and the quenching times. Tweaking this process will get you the properties you desire. Well, heat treatments are often performed on metals containing iron, which are known as ferrous metals. Annealing, hardening, normalizing, and tempering are done on such kinds of metals. Proper heat-treating equipment will be required so you can accurately control the factors around heating, cooling, and quenching. For instance, the furnace must be the proper size and type to control temperature, including the gas mixture in the heating chamber, and you need the appropriate quenching media to cool metal correctly. Purpose of Heat Treatment The following are the purposes of heat-treating metals: To improve ductility and toughness Increase the wear and corrosion resistance of a metal. Improve electrical and mechanical properties. Homogenize the structure to remove coring. Spheroidize tiny particles. Improve machinability and toughness. Grain size refinement. Relieving internal stresses. The Three Stages of Heat Treatment Heat treatment serves several purposes when it comes to metal, and these can be achieved in three stages. These three stages of heat treatment include heating, soaking, and cooling. 1. Heating Heating is the first stage in a heat-treating process. It is done to change the structure of alloys when heated to a specific temperature. The alloy is said to be at room temperature either as a solid solution, a mechanical mixture, or a combination of both. During this phase, the metal is gradually heated to a specific temperature to alter its internal microstructure and prepare it for quenching, annealing, tempering, or other processes. The key purpose of the heating phase is to soften or harden the metal, relieve internal stresses, refine grain structure, and prepare the metal for further mechanical or thermal treatment. Some important heating guidelines you should know are: Heating Rate: Should be slow and uniform to avoid thermal shock and distortion. Soaking Time: Once the desired temperature is reached, the metal is held (soaked) for a specific time to ensure the uniform temperature and microstructural changes. Atmosphere Control: Protective gases may be used to prevent oxidation or decarburization during heating. Finally, the heating phase is fundamental in heat treatment, as it determines how the metal's internal structure transforms. The exact temperature and time depend on the type of metal, desired outcome, and specific treatment process. The proper control of heating is important to achieve optimal mechanical properties without introducing defects. 2. Soaking The soaking phase is the second crucial step in the heat treatment process, following the heating phase. Once the metal reaches the desired temperature, it is held at that temperature for a specific period, which is known as soaking or holding time. Soaking is the stage at which the complete part of the heated metal completely changes its structure. The mass of the metal will determine the time it will be soaked. In other words, soaking is when a part of metal evenly turns red due to being subjected to heat for some time. The purpose of this phase is to allow uniform heat penetration throughout the entire part, ensure complete microstructural transformation, allow dissolution or redistribution of alloying elements, and finally to eliminate internal stresses and homogenize grain structure. It will take small parts at least 15-30 minutes to be fully soaked, medium parts take 30-60 minutes, while large or thick parts take 1-2 hours or more. But the general rule of thumb is 1 hour per inch of thickness. Take note of that! You should be aware that over-soaking can lead to grain growth, reducing strength and toughness, whilst, under-soaking results in incomplete transformation, leading to poor mechanical properties. This is to say uniform temperature must be maintained throughout the soaking period. The soaking phase is essential for achieving uniform metallurgical changes throughout the metal. By holding the metal at a specific temperature for a calculated time, internal structures can realign, dissolve, or transform as needed. Precision in both time and temperature is crucial for the success of the entire heat treatment process. You should learn about Metals with this detailed guide! 3. Cooling The cooling phase is the final stage of the heat treatment process. After the metal has been heated and soaked at the desired temperature, it is cooled in a controlled manner to achieve specific mechanical and structural properties. There are different ways of achieving this depending on the desired outcome. The rate and method of cooling directly influence the final hardness, strength, ductility, grain structure, and other characteristics of the metal. The purpose of this cooling phase is to lock in microstructural changes formed during heating and soaking, achieve desired mechanical properties like hardness or toughness, avoid internal stresses, distortion, or cracking, and determine whether the metal will be hard, soft, or tough. Cooling Rate Impact on Microstructure: Cooling Rate Microstructure Formed Resulting Properties Fast (quenching) Martensite Very hard but brittle Medium (air) Pearlite/Bainite Balanced strength and toughness Slow (furnace) Ferrite + Pearlite Soft, ductile, and machinable Types of Cooling Methods 1. Quenching: This is a fast way of cooling the metal, and the common mediums used are water, brine, or oil. The purpose is to increase hardness and strength (e.g., in steels) by transforming austenite into martensite. This is why it is used in hardening processes for high-carbon steels. However, cracking or warping might occur if not controlled. 2. Air Cooling: is a moderate cooling rate or method that uses the medium of still or forced air. It is used for normalizing and annealing to relieve stress while maintaining decent hardness. Structural steel and stainless steel are some metal materials that undergo these cooling methods. 3. Furnace Cooling: This cooling is a common slow cooling that is also called annealing or controlled cooling. Its purpose is to produce soft, ductile, and stress-free metals by cooling very slowly in the furnace. It is often used for low carbon steels, aluminum alloys, and copper. 4. Quenching + Tempering: This is a controlled reheating after cooling method performed to harden the metal (through quenching) and then reduce brittleness (through tempering). It is commonly done for tool steels, spring steels, and crankshafts. Some considerations you must follow during the cooling phase are the material type (e.g., carbon steel, aluminum), the desired mechanical properties, the risk of warping/cracking and the size and shape of the part. The cooling phase is just as important as heating. The purpose of this phase is to relieve internal stresses, soften the metal, and improve ductility. It is used for sheet metal, and parts that need further shaping or forming. Annealing Temperature Range for Softening Metals: Metal Type Temperature Range Low Carbon Steel 870°C-910°C (1600-1670°F) Stainless Steel 1040°C-1120°C (1900-2050°F) Aluminum Alloys 345°C - 415°C (650-780°F) Copper Alloys 425°C-650°C (800-1200°F) When performing annealing on steel, the soaking temperature should be from 870°C to 910°C (1600-1670°F). The soaking time should be 1 hour per inch of thickness to ensure full softening and stress relief. Hardening Hardening is a heat treatment process for enhancing a surface metal's hardness by heating and rapid cooling. It has to do with heating the material in a hardening furnace to a point that transforms its internal structure without melting it. Next, we hold the metal at the temperature for one hour per inch of thickness, followed by rapid cooling. There's a harder and more stable crystalline structure because of the rapid cooling. Hardening increases a metal's hardness and strength by heating followed by rapid cooling (usually via quenching). During the process, steel is heated above its critical temperature, held to form austenite, then quenched to trap carbon and form martensite. This is done to enhance wear resistance and load-bearing capacity. This is why the metal use in materials with durability like cutting tools, dies, and automotive and industrial parts. Hardening Temperature For Metal Types: Metal Type Temperature Range Medium/High Carbon Steel 760°C - 900°C (1400-1650°F) Tool Steel 900°C-1200°C (1650-2200°F) When hardening steel, the soaking temperature should be between 760°C and 900°C (1400-1650°F). The soaking time should be shorter than annealing, which is enough to allow the metal to reach its critical temperature. To increase hardness, the metal is heated in a furnace to a temperature above its critical temperature, held for a certain period, and then cooled rapidly. However, water, brine, and air can be used based on the material and the qualities you want. The quenching heat-treating process sets it apart from other processes because the metal is heated to a point just below the melting point at which the crystalline structure of the fluid. The properties you want will determine the method they will be held for. Afterward, it is quenched in one of the media to reduce the temperature of the material and yield the necessary internal structure. Just as explained earlier, quenching is the rapid cooling of a metal, usually after heating to a high temperature, to harden the material. The process is achieved by heating the metal to its austenitizing temperature and then rapidly cooling it in water, oil, or air. Its purpose is to increase hardness but also make the material brittle and it is used for high-strength tools, blades, and hardened steel parts. Stress Relieving This process has to do with heating the material above the point where the internal structure transforms and then air-cooling it at a particular rate. It allows for a more stable structure, reducing internal stress and enhancing the strength and hardness of the metal. It is particularly useful for metals that have been subjected to stress-inducing forming processes, such as machining, straightening, and rolling. To further explain, stress relieving is a heat treatment used to reduce internal residual stresses in metal without altering its structure drastically. The method helps to improve dimensional stability and reduces the risk of warping or cracking. It is used for welded structures, castings, and machined components. During the process, the metal is heated to a moderate temperature (typically 550°C - 700°C / 1020°F - 1290°F), held, and then cooled slowly. Aging Precipitation hardening or aging, is a heat treatment method used to increase the yield strength of malleable metals by producing uniformly dispersed particles within the grain structure. This process, which occurs after another heat treatment, reaches medium temperatures. Aging, also known as precipitation hardening, is a process used to increase the strength of a metal. It involves heating a metal to a temperature above its critical temperature, holding it for a certain period, and then cooling it. This process is used for a variety of materials, including aluminum alloys, stainless steel, and titanium alloys. Aging is commonly used for aerospace parts, high-strength aluminum components, carburization The metal undergoes heat treatment in the presence of an element that dissolves to produce carbon. The metal's surface absorbs the carbon that has been released. The surface becomes harder than the inner core due to an increase in carbon concentration. Carburization is a surface hardening process where carbon is diffused into the surface of low-carbon steel. During its process, the steel is heated (around 900°C - 950°C / 1650°F - 1750°F) in a carbon-rich environment (gas, solid, or liquid). It helps to produce a hard, wear-resistant surface while maintaining a tough, ductile core. This is why it is used in automobile industries for materials like gears, cams, crankshafts, and other parts subjected to surface wear. Tempering Tempering reduces excess hardness and brittleness during hardening, relieves internal stresses, and makes metals suitable for various applications. Temperatures are typically lower than hardening temperatures, with higher temperatures resulting in softer final workpieces. Cooling rate doesn't affect structure. It is a heat treatment process applied to hardened steel or iron to reduce brittleness and increase toughness. Tempering helps to soften the metal slightly to relieve internal stresses caused by hardening and is often used for tools, springs, and components requiring a balance of strength and flexibility. During the process, heat the metal to a temperature below its critical point (150°C - 650°C / 300°F - 1200°F), then cool it in air. The table below will help you have more understanding of the various methods of metal heat treatment: Process Purpose Cooling Method Typical Temp Range Tempering Reduce brittleness, increase toughness Air cooling 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench 800°C - 900°C (1450°F - 1650°F) Solution Annealing Soften metal by dissolving precipitates Heat and cool slowly 700°C - 900°C (1300°F - 1650°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Tempering Reduce brittleness, increase toughness Heat and cool slowly 150°C - 650°C (300°F - 1200°F) Carburization Surface hardening via carbon diffusion Quench after heating 900°C - 950°C (1650°F - 1750°F) Aging Strengthen alloys via precipitates Air cooling 120°C - 190°C (250°F - 375°F) Stress Relieving Reduce internal stress, relieve residual stresses Slow cooling 500°C - 650°C (900°F - 1200°F) Quenching Harden metal by forming martensite Rapid cooling 800°C - 900°C (1450°F - 1650°F) Annealing Soften metal, relieve stresses Slow cooling 700°C - 900°C (1300°F - 1650°F) Normalizing Refine grain structure, relieve stresses Air cooling 800°C - 900°C (1450°F - 1650°F) Case Hardening Surface hardening via carbon diffusion Quench after heating 800°C - 900°C (1450°F - 1650°F) Plasma Nitriding Surface hardening via nitrogen diffusion Heat in plasma 400°C - 600°C (750°F - 1100°F) Laser Heat Treatment Localized hardening via laser beam Heat and quench 1000°C - 1300°C (1800°F - 2350°F) Induction Heating Surface hardening via electromagnetic fields Heat and quench





heated above to a lower temperature and then cooled. This reduces brittleness while keeping much of the hardness. Normalizing Metal is heated above its critical point and cooled in air. This improves toughness and grain structure. Case Hardening This method hardens only the outer layer of the part, keeping the inside soft and flexible. It is used for gears and tools that need a tough surface. Conclusion Heat treating is a key process in mechanical engineering. It makes materials stronger, more flexible, or more durable based on the use. It helps improve the performance and life of metal components by changing their structure. Whether it's softening metal for machining or hardening it for cutting tools, heat treatment is necessary to ensure metals perform well under stress and over time. It plays an important role in almost every industry that uses metals. Heat treatment is the process of heating and cooling metals, using specific predetermined methods to obtain desired properties. Both ferrous, as well as non-ferrous metals, undergo heat treatment before putting them to use. Over time, a lot of different methods have been developed. Even today, metallurgists are constantly working to improve the outcomes and cost-efficiency of these processes. For that, they develop new schedules or cycles to produce a variety of grades. Each schedule refers to a different rate of heating, holding, and cooling the metal. These methods, when followed meticulously, can produce metals of different standards with remarkably specific physical and chemical properties. There are various reasons for carrying out heat treatment. Some procedures make the metal soft, while others increase hardness. They may also affect the electrical and heat conductivity of these materials. Some heat treatment methods relieve stresses induced in earlier cold working processes. Others develop desirable chemical properties to metals. Choosing the perfect method really comes down to the type of metal and the required properties. In some cases, a metal part may go through several heat treatment procedures. For instance, some superalloys used in the aircraft manufacturing industry may undergo up to six different heat-treating steps to optimize them for the application. In simple terms, heat treatment is the process of heating the metal, holding it at that temperature, and then cooling it back. During the process, the metal part will undergo changes in its mechanical properties. This is because the high temperature alters the microstructure of the metal. And microstructure plays an important role in the mechanical properties of a material. The final outcome depends on many different factors. These include the time of heating, time of keeping the metal part at a certain temperature, rate of cooling, surrounding conditions, and the parameters used on the heat treating media. The course of this process, the metal's properties will change. Among those properties are electrical resistance, magnetic an, hardness, toughness, ductility, brittleness, and wear resistance. As we already discussed, the microstructure of alloys will change during heat treatment. Heating is carried out in line with a prescribed thermal profile. An alloy may exist in one of three different states when heated. It may either be a mechanical mixture, a solid solution, or a combination of both. A mechanical mixture is analogous to a concrete mixture where cement binds sand and gravel together. Sand and gravel are still visible as separate particles. With metal alloys, the mechanical mixture is held together by the base metal. On the other hand, in a solid solution, all the components are mixed homogeneously. This means that they cannot be identified individually even under a microscope. Every state brings along different qualities. It is possible to change the state through heating according to the phase diagram. The cooling, though, determines the final outcome. It is possible for the alloy to end up in one of the three states, depending solely on the method. During the holding or soaking stage, the metal is kept at the achieved temperature. The duration of that depends on the requirements. For example, case hardening only requires structural changes to the surface of the metal in order to increase surface hardness. At the same time, other methods need uniform properties. In this case, the holding period is longer. The soaking time also depends on the material type and part size. Larger parts need more time when uniform properties are the objective. It just takes longer for the core of a large part to reach the required temperature. After the soaking stage is complete, the metal must be cooled in a prescribed manner. At this stage, too, structural changes occur. A solid solution on cooling may stay the same, become a mechanical mixture completely or partially, depending on various factors. Different media such as brine, water, oil or forced air control the rate of cooling. The sequence of cooling media named above is in decreasing order of effective rate of cooling. Brine absorbs heat fastest, while air is the slowest. It is also possible to use furnaces in the cooling process. The controlled environment allows for high precision when slow cooling is necessary. There are quite a few heat treating techniques to choose from, but they all bring along certain pros and cons. The most common heat treatment methods include: Annealing Normalizing Hardening Aging Stress relieving Tempering In annealing, the metal is heated beyond the upper critical temperature and then cooled at a slow rate. Annealing is carried out to soften the metal. It makes the metal more suitable for cold working and forming. It also enhances the metal's machinability, ductility and toughness. Annealing is also useful for relieving stresses in the part caused due to prior cold working processes. The plastic deformations present are removed during recrystallization when the metal temperature crosses the upper critical temperature. Metals may undergo a plethora of annealing techniques such as recrystallization annealing, full annealing, partial annealing, and final annealing. 2. Normalizing Normalizing is a heat treatment process used for relieving internal stresses caused by processes such as welding, casting, or quenching. In this process, the metal is heated to a temperature that is 40° C above its upper critical temperature. This temperature is higher than the one used for hardening or annealing. After holding it at this temperature for a designated period of time, it is cooled in air. Normalizing creates a uniform grain size and composition throughout the part. Normalized steels are harder and stronger than annealed steel. In fact, in its normalized form, steel is tougher than in any other condition. This is why parts that require impact strength or need to support massive external loads will almost always be normalized. The most common heat treatment process of all, hardening is used to increase the hardness of a metal. In some cases, only the surface may be hardened. A workpiece is hardened by heating it to the specified temperature, then cooling it rapidly by submerging it into a cooling medium. Oil, brine, or water may be used. The resulting part will have increased hardness and strength, but the brittleness increases too simultaneously. Case hardening is a type of hardening process in which only the outer layer of the workpiece is hardened. The process used is the same but as a thin outer layer is subjected to the process, the resultant workpiece has a hard outer layer but a softer core. This is common for shafts. A thin outer layer protects the material wear. When mounting a bearing to a shaft, it may otherwise damage the surface and dislocate some particles that then accelerate the wearing process. A hardened surface provides protection from that and the core still has the necessary properties to handle fatigue stresses. Aging or precipitation hardening is a heat treatment method mostly used to increase the yield strength of malleable metals. The process produces uniformly dispersed particles within a metal's grain structure which bring about changes in properties. Precipitation hardening usually comes after another heat treatment process that reaches higher temperatures. Aging, however, only elevates the temperature to medium levels and brings it down quickly again. Some materials may age naturally (at room temperature) while others only age artificially, i.e. at elevated temperatures. For naturally aging materials, it may be convenient to store them at lower temperatures. Stress-relieving is especially common for boiler parts, air bottles, accumulators, etc. This method takes the metal to a temperature just below its lower critical border. The cooling process is slow and therefore uniform. This is done to relieve stresses that have built-in up in the parts due to earlier processes such as forming, machining, rolling, or straightening. Tempering is the process of reducing excess hardness, and therefore brittleness, induced during the hardening process. Internal stresses are also relieved. Undergoing this process can make a metal suitable for many applications that need such properties. The temperatures are usually much lower than hardening temperatures. The higher the temperature used, the softer the final workpiece becomes. The rate of cooling does not affect the metal structure during tempering and usually, the metal cools in still air. In this heat treatment process, the metal is heated in the presence of another material that releases carbon on decomposition. The released carbon is absorbed into the surface of the metal. The carbon content of the surface increases, making it harder than the inner core. Although ferrous metals account for the majority of heat-treated materials, alloys of copper, magnesium, aluminum, nickel, brass, and titanium may also be heat treated. About 80% of heat-treated materials are different grades of steel. Ferrous metals that can be heat treated include cast iron, stainless steel, and various grades of tool steel. Processes like hardening, annealing, normalizing, stress relieving, case hardening, nitriding, and tempering are generally done on ferrous metals. Copper and copper alloys are subjected to heat treatment methods such as annealing, aging and quenching. Aluminum is suitable for heat treatment methods such as annealing, solution heat treating, natural and artificial aging. Heat treatment for aluminum is a precision process. Process scope must be established and it should be controlled carefully at each stage for the desired characteristics. Evidently, not all materials are suitable for the forms of heat treatment. Similarly, a single material will not necessarily benefit from each method. Therefore, every material should be studied separately to achieve the desired result. Using the phase diagrams and available information about the effect the aforementioned methods have is the starting point. Heat treatment is a critical and complex element in the manufacturing of gears that greatly impacts how each will perform in transmitting power or carrying motion to other components in an assembly. Heat treatments optimize the performance and extend the life of gears in service by altering their chemical, metallurgical, and physical properties. These properties are determined by considering the gear's geometry, power transmission requirements, stresses at different points within a gear under load, load cycling rates, material type, mating part designs, and other operating conditions. Heat treatments improve physical properties such as surface hardness, which impacts wear resistance to prevent tooth and bearing surfaces from simply wearing out. Heat treatments also improve a gear's fatigue life by generating subsurface compressive stresses to prevent pitting and deformation from high contact stresses on gear teeth. These same compressive stresses prevent fatigue failures in gear roots from cyclic tooth bending. Physical properties such as surface hardness, core hardness, case depth, ductility, strength, wear resistance and compressive stress profiles can vary greatly depending on the type of heat treatment applied. For any given type of heat treatment the results can be tailored by modifying process parameters such as heating source, temperatures, cycle times, atmospheres, quench media, and tempering cycles to meet specific application requirements. Figure 1: Typical press quench equipment and tooling design (Source: The Heat Treat Doctor: Fundamentals of Press Quenching by Dan Herring, Industrial Heating April, 1995). Besides selecting heat treatments that will produce a set of desired physical properties, manufacturing engineers want to minimize distortion of dimensions from treatment such that final proper fit into a gearbox can be achieved. Many gears are machined into an oversized condition prior to heat treatment so that a planned amount of grind stock may be removed after the process in order to meet dimensional requirements. By selecting heat treatment processes where distortion is reduced, the amount of grind stock needed may be reduced to minimize machining on hardened surfaces after heat treatment and thereby reduce the overall costs of manufacturing. Removing too much of the outermost portion of a case hardened gear that distorted excessively will also negatively impact the fatigue properties and wear life performance. Some heat treatment processes are designed to treat the entire surface of a gear, while others are selective in nature. Induction hardening or selective heating may be employed to harden just the gear teeth only, which can be an effective method of reducing the distortion in a gear. Masking of journals and keyways may be employed in case hardening processes to keep them soft and allow for easier grind stock removal after heat treatment. Reduction of distortion by intelligent heat treatment process design allows manufacturing engineers to improve the performance and/or reduce the overall costs of manufacturing a gear. Fig. 2: Two fully automated low pressure carburizing furnace lines (Bodycote-Livonia, Michigan). In all cases, gear design engineers understand that heat treatments play a complex and vital role in both the ease of manufacturing and the performance of the gears they make. Today, many options exist for the heat treatment of gears. Proper selection and design of the heat treatment process can greatly affect performance, ease of manufacture, and economics of a component. This paper will focus on a variety of different processes and highlight some benefits and disadvantages of each. Heat Treating Basics To understand heat treating, a basic knowledge of metallurgy is needed. Iron, when combined with small percentages of carbon, forms steel. Plain carbon steels typically contain 1 percent or less carbon in combination with iron. The maximum hardness that any plain carbon steel can achieve during heat treatment is primarily a function of its carbon content. Higher carbon content steels are capable of being hardened to higher hardness values than lower carbon content steels. To make alloy steels, small percentages of other elements such as Cr, Ni, Mo, Si, B, V, Ti, Al, Nb, W, and Cu (to name the most common) are added to steel. These alloying elements are added in order to increase hardenability or enhance specific properties such as toughness or resistance to softening from heat build-up. For heat treaters the higher hardenability allows for slower quenching, which means distortion can be kept to low or lower levels in more highly alloyed steels. Steels can be annealed by thermally processing at a high temperature and slow cooling to soften it. In this soft and malleable state it can be machined, formed, hobbed, and ground easily into a desired shape. What makes steel industrially important is that it can be hardened after the material has been formed or shaped in the soft state to a desired geometry. By use of a thermal processing cycle where steel is heated to austenitizing temperatures and rapidly quenched, the near-finished components can be hardened to improve wear resistance, strength, and hardness. After quenching to the maximum hardness achievable, which is determined by the steel's carbon content, the steel may then be tempered down to a lower hardness to improve ductility and toughness at the expense of slightly reducing the strength, hardness, and wear characteristics of the material. Figure 3: Hardness and compressive stress profiles generated by LPC (compare to Fig. 4). What actually occurs in steel during heat treating are phase transformations as atoms rearrange themselves into different crystal structures. The starting point of most heat treated parts is an annealed material. In fact, when purchasing steel it is generally in the annealed condition. An annealed structure is a combination of primarily ferrite (Fe<sub>2</sub>, pure iron) and iron carbide (Fe<sub>3</sub>C, cementite). These will be in the form of alternating layers of ferrite and Fe<sub>3</sub>C spheres or spherulites with dispersed Fe<sub>3</sub>C spheres or spherulites (spheroidized structure). When steel is heated above its austenitizing temperature, it transforms into the austenite structure. An approximate austenitizing temperature for most plain carbon steels is around 1330°F and varies by exact grade of steel. Once full transformation of the steel to an austenite structure has occurred the austenite may be quenched (cooled rapidly), and that austenitic structure will transform to a martensite structure. This transformation of austenite to martensite is the hardening process. The martensite structure yields the highest hardness and tensile strength properties of any structure for that steel. Producing a martensitic structure from austenite is the goal in hardening heat treatment of steels. One critical aspect of this hardening process is the cooling rate employed during quenching. Each grade of steel requires that a certain minimum cooling rate be achieved during quenching or the transformation from austenite to martensite will not occur. Austenitized steels held at high temperature and quenched too slowly down to ambient temperature will not transform from austenite to a martensitic structure. They will instead revert back a softer mix of ferrite and cementite again. Table 1 summarizes the methods in common use today for heat treatment of gears. Each method has its place; some are perfect for high volumes, while others are practical only on a piece-by-piece basis. Some improve all metallurgical properties, while others improve only one or two. Table 1: Common heat-treating methods for gears. Neutral Hardening There are two general classifications of heat treatments used for hardening steels: neutral hardening, and case hardening. Neutral hardening refers to maintaining the carbon potential of the atmosphere at the same percentage as the carbon in the steel during the hardening cycle. This means that carbon is entering and leaving the surface of the steel at the same rate, and no net gain or net loss of carbon atoms inside the surface of the steel occurs. Many gears are neutral hardened, but for the most demanding applications case hardening processes, such as carburizing and nitriding, are the preferred methods due to their improved wear characteristics and mechanical properties. Fig. 4: Hardness and compressive stress profiles generated by atmosphere carburizing (compare to Fig. 3). Atmosphere Carburizing Carburizing, the most widely used form of surface hardening, is the process of diffusing carbon into the surface of low carbon steel at elevated temperatures. This results in a high carbon case forming just inside the surface of a low carbon component. During quenching from austenitizing temperatures the austenite will transform to martensite, and the higher carbon case will have a high hardness while the lower carbon core material will have a lower hardness. The goal of this process is to produce a hard, strong, wear resistant outer surface while retaining a softer, ductile tough core. When austenite transforms to martensite during quenching, a volume expansion occurs in the material and it grows. The volumetric expansion in the case is greater than the volume expansion in the lower carbon, lower hardness core structure. This difference in size changes puts the carburized surface of the part into a state of compression, which makes it stronger. For example, when a force is applied to a gear tooth, it first has to overcome these compressive forces before beginning to put the surface of the tooth in tension. In order to deform this material, it requires a force that exceeds the combination of overcoming the compressive stresses present in addition to the normal yield strength of the material. These compressive stresses caused by differences in volume expansion rates between the case and core improves the overall tensile and yield strength of the carburized case inside a gear tooth. It is these compressive stresses that resist deformation from high contact stresses present as gear teeth press and roll against each other. These compressive stresses also increase fatigue life by helping to prevent cracking in tooth roots as the teeth are cyclically loaded and unloaded with bending stresses. The high carbon, high hardness surface of the carburized case also resists wear and scoring caused by friction as gear teeth rub and wear against each other. One can't discuss heat treating gears without discussing distortion, which occurs for a variety of reasons. One source is pre-existing residual stresses present in the material caused by prior operations such as steelmaking, rolling, forming, forging, casting, machining, and grinding. As the material begins to heat treat during carburizing, these residual stresses present in the material relieve and cause the gears to distort if these stresses were large or non-uniform. A secondary source of distortion is high temperature creep during processing. Gravity is the enemy of many gear designs during thermal processing, especially in carburizing, where high temperatures and long processing times are the norm. At high temperatures, steel has little strength and can sag and bend under gravity's force if sections of a part are not properly supported or components not stood up or hung perfectly straight. Spending the extra time to fixture parts correctly and designing customized fixtures to properly support a gear during exposure to high temperatures can save many hours of straightening and machining afterwards. Some part shapes such as long shafts are best racked in vertical orientations to maintain straightness while other shapes such as rings are better if laid flat horizontally to maintain roundness. Selection and experience in designing heat treatment fixtures can dramatically affect the results. A third source of distortion is quenching, which is typically the main offender in distorting parts during heat treatment. The ideal quench is the slowest quench that will uniformly pull heat out of the part, while still fully transforming the surface to martensite and achieving the desired case and core properties. This sounds easy enough, but in practice it can be quite difficult given the design and complex shape of many gears. Due to variations in customers' part geometries, limitations in fixture designs, non-uniform quench tank agitation, and part-to-part or part-to-fixture interactions, it is the most difficult distortion mechanism to resolve and predict. Even within a single part it's possible to have some thinner sections of a component cool faster than thicker sections causing one area to transform earlier than another and warp dimensions as the transformations with their associated volume expansions occur at different times during a quench. When distortion occurs to an unacceptable degree, solutions need to be found. After exhausting all the variations of processing parameters, fixturing methods, quench modifications, and ensuring parts are free from stress prior to heat treatment, other options need to be considered. This can be as simple as a straightening step, or as difficult as re-engineering the part. Some other methods of heat treating include: Case Hardening Case hardening is a process of diffusing carbon into the surface of low carbon steel at elevated temperatures. This results in a high carbon case forming just inside the surface of a low carbon component. During quenching from austenitizing temperatures the austenite will transform to martensite, and the higher carbon case will have a high hardness while the lower carbon core material will have a lower hardness. The goal of this process is to produce a hard, strong, wear resistant outer surface while retaining a softer, ductile tough core. When austenite transforms to martensite during quenching, a volume expansion occurs in the material and it grows. The volumetric expansion in the case is greater than the volume expansion in the lower carbon, lower hardness core structure. This difference in size changes puts the carburized surface of the part into a state of compression, which makes it stronger. For example, when a force is applied to a gear tooth, it first has to overcome these compressive forces before beginning to put the surface of the tooth in tension. In order to deform this material, it requires a force that exceeds the combination of overcoming the compressive stresses present in addition to the normal yield strength of the material. These compressive stresses caused by differences in volume expansion rates between the case and core improves the overall tensile and yield strength of the carburized case inside a gear tooth. It is these compressive stresses that resist deformation from high contact stresses present as gear teeth press and roll against each other. These compressive stresses also increase fatigue life by helping to prevent cracking in tooth roots as the teeth are cyclically loaded and unloaded with bending stresses. The high carbon, high hardness surface of the carburized case also resists wear and scoring caused by friction as gear teeth rub and wear against each other. One can't discuss heat treating gears without discussing distortion, which occurs for a variety of reasons. One source is pre-existing residual stresses present in the material caused by prior operations such as steelmaking, rolling, forming, forging, casting, machining, and grinding. As the material begins to heat treat during carburizing, these residual stresses present in the material relieve and cause the gears to distort if these stresses were large or non-uniform. A secondary source of distortion is high temperature creep during processing. Gravity is the enemy of many gear designs during thermal processing, especially in carburizing, where high temperatures and long processing times are the norm. At high temperatures, steel has little strength and can sag and bend under gravity's force if sections of a part are not properly supported or components not stood up or hung perfectly straight. Spending the extra time to fixture parts correctly and designing customized fixtures to properly support a gear during exposure to high temperatures can save many hours of straightening and machining afterwards. Some part shapes such as long shafts are best racked in vertical orientations to maintain straightness while other shapes such as rings are better if laid flat horizontally to maintain roundness. Selection and experience in designing heat treatment fixtures can dramatically affect the results. A third source of distortion is quenching, which is typically the main offender in distorting parts during heat treatment. The ideal quench is the slowest quench that will uniformly pull heat out of the part, while still fully transforming the surface to martensite and achieving the desired case and core properties. This sounds easy enough, but in practice it can be quite difficult given the design and complex shape of many gears. Due to variations in customers' part geometries, limitations in fixture designs, non-uniform quench tank agitation, and part-to-part or part-to-fixture interactions, it is the most difficult distortion mechanism to resolve and predict. Even within a single part it's possible to have some thinner sections of a component cool faster than thicker sections causing one area to transform earlier than another and warp dimensions as the transformations with their associated volume expansions occur at different times during a quench. When distortion occurs to an unacceptable degree, solutions need to be found. After exhausting all the variations of processing parameters, fixturing methods, quench modifications, and ensuring parts are free from stress prior to heat treatment, other options need to be considered. This can be as simple as a straightening step, or as difficult as re-engineering the part. Some other methods of heat treating include: Case Hardening Case hardening is a process of diffusing carbon into the surface of low carbon steel at elevated temperatures. This results in a high carbon case forming just inside the surface of a low carbon component. During quenching from austenitizing temperatures the austenite will transform to martensite, and the higher carbon case will have a high hardness while the lower carbon core material will have a lower hardness. The goal of this process is to produce a hard, strong, wear resistant outer surface while retaining a softer, ductile tough core. When austenite transforms to martensite during quenching, a volume expansion occurs in the material and it grows. The volumetric expansion in the case is greater than the volume expansion in the lower carbon, lower hardness core structure. This difference in size changes puts the carburized surface of the part into a state of compression, which makes it stronger. For example, when a force is applied to a gear tooth, it first has to overcome these compressive forces before beginning to put the surface of the tooth in tension. In order to deform this material, it requires a force that exceeds the combination of overcoming the compressive stresses present in addition to the normal yield strength of the material. These compressive stresses caused by differences in volume expansion rates between the case and core improves the overall tensile and yield strength of the carburized case inside a gear tooth. It is these compressive stresses that resist deformation from high contact stresses present as gear teeth press and roll against each other. These compressive stresses also increase fatigue life by helping to prevent cracking in tooth roots as the teeth are cyclically loaded and unloaded with bending stresses. The high carbon, high hardness surface of the carburized case also resists wear and scoring caused by friction as gear teeth rub and wear against each other. One can't discuss heat treating gears without discussing distortion, which occurs for a variety of reasons. One source is pre-existing residual stresses present in the material caused by prior operations such as steelmaking, rolling, forming, forging, casting, machining, and grinding. As the material begins to heat treat during carburizing, these residual stresses present in the material relieve and cause the gears to distort if these stresses were large or non-uniform. A secondary source of distortion is high temperature creep during processing. Gravity is the enemy of many gear designs during thermal processing, especially in carburizing, where high temperatures and long processing times are the norm. At high temperatures, steel has little strength and can sag and bend under gravity's force if sections of a part are not properly supported or components not stood up or hung perfectly straight. Spending the extra time to fixture parts correctly and designing customized fixtures to properly support a gear during exposure to high temperatures can save many hours of straightening and machining afterwards. Some part shapes such as long shafts are best racked in vertical orientations to maintain straightness while other shapes such as rings are better if laid flat horizontally to maintain roundness. Selection and experience in designing heat treatment fixtures can dramatically affect the results. A third source of distortion is quenching, which is typically the main offender in distorting parts during heat treatment. The ideal quench is the slowest quench that will uniformly pull heat out of the part, while still fully transforming the surface to martensite and achieving the desired case and core properties. This sounds easy enough, but in practice it can be quite difficult given the design and complex shape of many gears. Due to variations in customers' part geometries, limitations in fixture designs, non-uniform quench tank agitation, and part-to-part or part-to-fixture interactions, it is the most difficult distortion mechanism to resolve and predict. Even within a single part it's possible to have some thinner sections of a component cool faster than thicker sections causing one area to transform earlier than another and warp dimensions as the transformations with their associated volume expansions occur at different times during a quench. When distortion occurs to an unacceptable degree, solutions need to be found. After exhausting all the variations of processing parameters, fixturing methods, quench modifications, and ensuring parts are free from stress prior to heat treatment, other options need to be considered. This can be as simple as a straightening step, or as difficult as re-engineering the part. Some other methods of heat treating include: Case Hardening Case hardening is a process of diffusing carbon into the surface of low carbon steel at elevated temperatures. This results in a high carbon case forming just inside the surface of a low carbon component. During quenching from austenitizing temperatures the austenite will transform to martensite, and the higher carbon case will have a high hardness while the lower carbon core material will have a lower hardness. The goal of this process is to produce a hard, strong, wear resistant outer surface while retaining a softer, ductile tough core. When austenite transforms to martensite during quenching, a volume expansion occurs in the material and it grows. The volumetric expansion in the case is greater than the volume expansion in the lower carbon, lower hardness core structure. This difference in size changes puts the carburized surface of the part into a state of compression, which makes it stronger. For example, when a force is applied to a gear tooth, it first has to overcome these compressive forces before beginning to put the surface of the tooth in tension. In order to deform this material, it requires a force that exceeds the combination of overcoming the compressive stresses present in addition to the normal yield strength of the material. These compressive stresses caused by differences in volume expansion rates between the case and core improves the overall tensile and yield strength of the carburized case inside a gear tooth. It is these compressive stresses that resist deformation from high contact stresses present as gear teeth press and roll against each other. These compressive stresses also increase fatigue life by helping to prevent cracking in tooth roots as the teeth are cyclically loaded and unloaded with bending stresses. The high carbon, high hardness surface of the carburized case also resists wear and scoring caused by friction as gear teeth rub and wear against each other. One can't discuss heat treating gears without discussing distortion, which occurs for a variety of reasons. One source is pre-existing residual stresses present in the material caused by prior operations such as steelmaking, rolling, forming, forging, casting, machining, and grinding. As the material begins to heat treat during carburizing, these residual stresses present in the material relieve and cause the gears to distort if these stresses were large or non-uniform. A secondary source of distortion is high temperature creep during processing. Gravity is the enemy of many gear designs during thermal processing, especially in carburizing, where high temperatures and long processing times are the norm. At high temperatures, steel has little strength and can sag and bend under gravity's force if sections of a part are not properly supported or components not stood up or hung perfectly straight. Spending the extra time to fixture parts correctly and designing customized fixtures to properly support a gear during exposure to high temperatures can save many hours of straightening and machining afterwards. Some part shapes such as long shafts are best racked in vertical orientations to maintain straightness while other shapes such as rings are better if laid flat horizontally to maintain roundness. Selection and experience in designing heat treatment fixtures can dramatically affect the results. A third source of distortion is quenching, which is typically the main offender in distorting parts during heat treatment. The ideal quench is the slowest quench that will uniformly pull heat out of the part, while still fully transforming the surface to martensite and achieving the desired case and core properties. This sounds easy enough, but in practice it can be quite difficult given the design and complex shape of many gears. Due to variations in customers' part geometries, limitations in fixture designs, non-uniform quench tank agitation, and part-to-part or part-to-fixture interactions, it is the most difficult distortion mechanism to resolve and predict. Even within a single part it's possible to have some thinner sections of a component cool faster than thicker sections causing one area to transform earlier than another and warp dimensions as the transformations with their associated volume expansions occur at different times during a quench. When distortion occurs to an unacceptable degree, solutions need to be found. After exhausting all the variations of processing parameters, fixturing methods, quench modifications, and ensuring parts are free from stress prior to heat treatment, other options need to be considered. This can be as simple as a straightening step, or as difficult as re-engineering the part. Some other methods of heat treating include: Case Hardening Case hardening is a process of diffusing carbon into the surface of low carbon steel at elevated temperatures. This results in a high carbon case forming just inside the surface of a low carbon component. During quenching from austenitizing temperatures the austenite will transform to martensite, and the higher carbon case will have a high hardness while the lower carbon core material will have a lower hardness. The goal of this process is to produce a hard, strong, wear resistant outer surface while retaining a softer, ductile tough core. When austenite transforms to martensite during quenching, a volume expansion occurs in the material and it grows. The volumetric expansion in the case is greater than the volume expansion in the lower carbon, lower hardness core structure. This difference in size changes puts the carburized surface of the part into a state of compression, which makes it stronger. For example, when a force is applied to a gear tooth, it first has to overcome these compressive forces before beginning to put the surface of the tooth in tension. In order to deform this material, it requires a force that exceeds the combination of overcoming the compressive stresses present in addition to the normal yield strength of the material. These compressive stresses caused by differences in volume expansion rates between the case and core improves the overall tensile and yield strength of the carburized case inside a gear tooth. It is these compressive stresses that resist deformation from high contact stresses present as gear teeth press and roll against each other. These compressive stresses also increase fatigue life by helping to prevent cracking in tooth roots as the teeth are cyclically loaded and unloaded with bending stresses. The high carbon, high hardness surface of the carburized case also resists wear and scoring caused by friction as gear teeth rub and wear against each other. One can't discuss heat treating gears without discussing distortion, which occurs for a variety of reasons. One source is pre-existing residual stresses present in the material caused by prior operations such as steelmaking, rolling, forming, forging, casting, machining, and grinding. As the material begins to heat treat during carburizing, these residual stresses present in the material relieve and cause the gears to distort if these stresses were large or non-uniform. A secondary source of distortion is high temperature creep during processing. Gravity is the enemy of many gear designs during thermal processing, especially in carburizing, where high temperatures and long processing times are the norm. At high temperatures, steel has little strength and can sag and bend under gravity's force if sections of a part are not properly supported or components not stood up or hung perfectly straight. Spending the extra time to fixture parts correctly and designing customized fixtures to properly support a gear during exposure to high temperatures can save many hours of straightening and machining afterwards. Some part shapes such as long shafts are best racked in vertical orientations to maintain straightness while other shapes such as rings are better if laid flat horizontally to maintain roundness. Selection and experience in designing heat treatment fixtures can dramatically affect the results. A third source of distortion is quenching, which is typically the main offender in distorting parts during heat treatment. The ideal quench is the slowest quench that will uniformly pull heat out of the part, while still fully transforming the surface to martensite and achieving the desired case and core properties. This sounds easy enough, but in practice it can be quite difficult given the design and complex shape of many gears. Due to variations in customers' part geometries, limitations in fixture designs, non-uniform quench tank agitation, and part-to-part or part-to-fixture interactions, it is the most difficult distortion mechanism to resolve and predict. Even within a single part it's possible to have some thinner sections of a component cool faster than thicker sections causing one area to transform earlier than another and warp dimensions as the transformations with their associated volume expansions occur at different times during a quench. When distortion occurs to an unacceptable degree, solutions need to be found. After exhausting all the variations of processing parameters, fixturing methods, quench modifications, and ensuring parts are free from stress prior to heat treatment, other options need to be considered. This can be as simple as a straightening step, or as difficult as re-engineering the part. Some other methods of heat treating include: Case Hardening Case hardening is a process of diffusing carbon into the surface of low carbon steel at elevated temperatures. This results in a high carbon case forming just inside the surface of a low carbon component. During quenching from austenitizing temperatures the austenite will transform to martensite, and the higher carbon case will have a high hardness while the lower carbon core material will have a lower hardness. The goal of this process is to produce a hard, strong, wear resistant outer surface while retaining a softer, ductile tough core. When austenite transforms to martensite during quenching, a volume expansion occurs in the material and it grows. The volumetric expansion in the case is greater than the volume expansion in the lower carbon, lower hardness core structure. This difference in size changes puts the carburized surface of the part into a state of compression, which makes it stronger. For example, when a force is applied to a gear tooth, it first has to overcome these compressive forces before beginning to put the surface of the tooth in tension. In order to deform this material, it requires a force that exceeds the combination of overcoming the compressive stresses present in addition to the normal yield strength of the material. These compressive stresses caused by differences in volume expansion rates between the case and core improves the overall tensile and yield strength of the carburized case inside a gear tooth. It is these compressive stresses that resist deformation from high contact stresses present as gear teeth press and roll against each other. These compressive stresses also increase fatigue life by helping to prevent cracking in tooth roots as the teeth are cyclically loaded and unloaded with bending stresses. The high carbon, high hardness surface of the carburized case also resists wear and scoring caused by friction as gear teeth rub and wear against each other. One can't discuss heat treating gears without discussing distortion, which occurs for a variety of reasons. One source is pre-existing residual stresses present in the material caused by prior operations such as steelmaking, rolling, forming, forging, casting, machining, and grinding. As the material begins to heat treat during carburizing, these residual stresses present in the material relieve and cause the gears to distort if these stresses were large or non-uniform. A secondary source of distortion is high temperature creep during processing. Gravity is the enemy of many gear designs during thermal processing, especially in carburizing, where high temperatures and long processing times are the norm. At high temperatures, steel has little strength and can sag and bend under gravity's force if sections of a part are not properly supported or components not stood up or hung perfectly straight. Spending the extra time to fixture parts correctly and designing customized fixtures to properly support a gear during exposure to high temperatures can save many hours of straightening and machining afterwards. Some part shapes such as long shafts are best racked in vertical orientations to maintain straightness while other shapes such as rings are better if laid flat horizontally to maintain roundness. Selection and experience in designing heat treatment fixtures can dramatically affect the results. A third source of distortion is quenching, which is typically the main offender in distorting parts during heat treatment. The ideal quench is the slowest quench that will uniformly pull heat out of the part, while still fully transforming the surface to martensite and achieving the desired case and core properties. This sounds easy enough, but in practice it can be quite difficult given the design and complex shape of many gears. Due to variations in customers' part geometries, limitations in fixture designs, non-uniform quench tank agitation, and part-to-part or part-to-fixture interactions, it is the most difficult distortion mechanism to resolve and predict. Even within a single part it's possible to have some thinner sections of a component cool faster than thicker sections causing one area to transform earlier than another and warp dimensions as the transformations with their associated volume expansions occur at different times during a quench. When distortion occurs to an unacceptable degree, solutions need to be found. After exhausting all the variations of processing parameters, fixturing methods, quench modifications, and ensuring parts are free from stress prior to heat treatment, other options need to be considered. This can be as simple as a straightening step, or as difficult as re-engineering the part. Some other methods of heat treating include: Case Hardening Case hardening is a process of diffusing carbon into the surface of low carbon steel at elevated temperatures. This results in a high carbon case forming just inside the surface of a low carbon component. During quenching from austenitizing temperatures the austenite will transform to martensite, and the higher carbon case will have a high hardness while the lower carbon core material will have a lower hardness. The goal of this process is to produce a hard, strong, wear resistant outer surface while retaining a softer, ductile tough core. When austenite transforms to martensite during quenching, a volume expansion occurs in the material and it grows. The volumetric expansion in the case is greater than the volume expansion in the lower carbon, lower hardness core structure. This difference in size changes puts the carburized surface of the part into a state of compression, which makes it stronger. For example, when a force is applied to a gear tooth, it first has to overcome these compressive forces before beginning to put the surface of the tooth in tension. In order to deform this material, it requires a force that exceeds the combination of overcoming the compressive stresses present in addition to the normal yield strength of the material. These compressive stresses caused by differences in volume expansion rates between the case and core improves the overall tensile and yield strength of the carburized case inside a gear tooth. It is these compressive stresses that resist deformation from high contact stresses present as gear teeth press and roll against each other. These compressive stresses also increase fatigue life by helping to prevent cracking in tooth roots as the teeth are cyclically loaded and unloaded with bending stresses. The high carbon, high hardness surface of the carburized case also resists wear and scoring caused by friction as gear teeth rub and wear against each other. One can't discuss heat treating gears without discussing distortion, which occurs for a variety of reasons. One source is pre-existing residual stresses present in the material caused by prior operations such as steelmaking, rolling, forming, forging, casting, machining, and grinding. As the material begins to heat treat during carburizing, these residual stresses present in the material relieve and cause the gears to distort if these stresses were large or non-uniform. A secondary source of distortion is high temperature creep during processing. Gravity is the enemy of many gear designs during thermal processing, especially in carburizing, where high temperatures and long processing times are the norm. At high temperatures, steel has little strength and can sag and bend under gravity's force if sections of a part are not properly supported or components not stood up or hung perfectly straight. Spending the extra time to fixture parts correctly and designing customized fixtures to properly support a gear during exposure to high temperatures can save many hours of straightening and machining afterwards. Some part shapes such as long shafts are best racked in vertical orientations to maintain straightness while other shapes such as rings are better if laid flat horizontally to maintain roundness. Selection and experience in designing heat treatment fixtures can dramatically affect the results. A third source of distortion is quenching, which is typically the main offender in distorting parts during heat treatment. The ideal quench is the slowest quench that will uniformly pull heat out of the part, while still fully transforming the surface to martensite and achieving the desired case and core properties. This sounds easy enough, but in practice it can be quite difficult given the design and complex shape of many gears. Due to variations in customers' part geometries, limitations in fixture designs, non-uniform quench tank agitation, and part-to-part or part-to-fixture interactions, it is the most difficult distortion mechanism to resolve and predict. Even within a single part it's possible to have some thinner sections of a component cool faster than thicker sections causing one area to transform earlier than another and warp dimensions as the transformations with their associated volume expansions occur at different times during a quench. When distortion occurs to an unacceptable degree, solutions need to be found. After exhausting all the variations of processing parameters, fixturing methods, quench modifications, and ensuring parts are free from stress prior to heat treatment, other options need to be considered. This can be as simple as a straightening step, or as difficult as re-engineering the part. Some other methods of heat treating include: Case Hardening Case hardening is a process of diffusing carbon into the surface of low carbon steel at elevated temperatures. This results in a high carbon case forming just inside the surface of a low carbon component. During quenching from austenitizing temperatures the austenite will transform to martensite, and the higher carbon case will have a high hardness while the lower carbon core material will have a lower hardness. The goal of this process is to produce a hard, strong, wear resistant outer surface while retaining a softer, ductile tough core. When austenite transforms to martensite during quenching, a volume expansion occurs in the material and it grows. The volumetric expansion in the case is greater than the volume expansion in the lower carbon, lower hardness core structure. This difference in size changes puts the carburized surface of the part into a state of compression, which makes it stronger. For example, when a force is applied to a gear tooth, it first has to overcome these compressive forces before beginning to put the surface of the tooth in tension. In order to deform this material, it requires a force that exceeds the combination of overcoming the compressive stresses present in addition to the normal yield strength of the material. These compressive stresses caused by differences in volume expansion rates between the case and core improves the overall tensile and yield strength of the carburized case inside a gear tooth. It is these compressive stresses that resist deformation from high contact stresses present as gear teeth press and roll against each other. These compressive stresses also increase fatigue life by helping to prevent cracking in tooth roots as the teeth are cyclically loaded and unloaded with bending stresses. The high carbon, high hardness surface of the carburized case also resists wear and scoring caused by friction as gear teeth rub and wear against each other. One can't discuss heat treating gears without discussing distortion, which occurs for a variety of reasons. One source is pre-existing residual stresses present in the material caused by prior operations such as steelmaking, rolling, forming, forging, casting, machining, and grinding. As the material begins to heat treat during carburizing, these residual stresses present in the material relieve and cause the gears to distort if these stresses were large or non-uniform. A secondary source of distortion is high temperature creep during processing. Gravity is the enemy of many gear designs during thermal processing, especially in carburizing, where high temperatures and long processing times are the norm. At high temperatures, steel has little strength and can sag and bend under gravity's force if sections of a part are not properly supported or components not stood up or hung perfectly straight. Spending the extra time to fixture parts correctly and designing customized fixtures to properly support a gear during exposure to high temperatures can save many hours of straightening and machining afterwards. Some part shapes such as long shafts are best racked in vertical orientations to maintain straightness while other shapes such as rings are better if laid flat horizontally to maintain roundness. Selection and experience in designing heat treatment fixtures can dramatically affect the results. A third source of distortion is quenching, which is typically the main offender in distorting parts during heat treatment. The ideal quench is the slowest quench that will uniformly pull heat out of the part, while still fully transforming the surface to martensite and achieving the desired case and core properties. This sounds easy enough, but in practice it can be quite difficult given the design and complex shape of many gears. Due to variations in customers' part geometries, limitations in fixture designs, non-uniform quench tank agitation, and part-to-part or part-to-fixture interactions, it is the most difficult distortion mechanism to resolve and predict. Even within a single part it's possible to have some thinner sections of a component cool faster than thicker sections causing one area to transform earlier than another and warp dimensions as the transformations with their associated volume expansions occur at different times during a quench. When distortion occurs to an unacceptable degree, solutions need to be found. After exhausting all the variations of processing parameters, fixturing methods, quench modifications, and ensuring parts are free from stress prior to heat treatment, other options need to be considered. This can be as simple as a straightening step, or as difficult as re-engineering the part. Some other methods of heat treating include: Case Hardening Case hardening is a process of diffusing carbon into the surface of low carbon steel at elevated temperatures. This results in a high carbon case forming just inside the surface of a low carbon component. During quenching from austenitizing temperatures the austenite will transform to martensite, and the higher carbon case will have a high hardness while the lower carbon core material will have a lower hardness. The goal of this process is to produce a hard, strong, wear resistant outer surface while retaining a softer, ductile tough core. When austenite transforms to martensite during quenching, a volume expansion occurs in the material and it grows. The volumetric expansion in the case is greater than the volume expansion in the lower carbon, lower hardness core structure. This difference in size changes puts the carburized surface of the part into a state of compression, which makes it stronger. For example, when a force is applied to a gear tooth, it first has to overcome these compressive forces before beginning to put the surface of the tooth in tension. In order to deform this material, it requires a force that exceeds the combination of overcoming the compressive stresses present in addition to the normal yield strength of the material. These compressive stresses caused by differences in volume expansion rates between the case and core improves the overall tensile and yield strength of the carburized case inside a gear tooth. It is these compressive stresses that resist deformation from high contact stresses present as gear teeth press and roll against each other. These compressive stresses also increase fatigue life by helping to prevent cracking in tooth roots as the teeth are cyclically loaded and unloaded with bending stresses. The high carbon, high hardness surface of the carburized case also resists wear and scoring caused by friction as gear teeth rub and wear against each other. One can't discuss heat treating gears without discussing distortion, which occurs for a variety of reasons. One source is pre-existing residual stresses present in the material caused by prior operations such as steelmaking, rolling, forming, forging, casting, machining, and grinding. As the material begins to heat treat during carburizing, these residual stresses present in the material relieve and cause the gears to distort if these stresses were large or non-uniform. A secondary source of distortion is high temperature creep during processing. Gravity is the enemy of many gear designs during thermal processing, especially in carburizing, where high temperatures and long processing times are the norm. At high temperatures, steel has little strength and can sag and bend under gravity's force if sections of a part are not properly supported or components not stood up or hung perfectly straight. Spending the extra time to fixture parts correctly and designing customized fixtures to properly support a gear during exposure to high temperatures can save many hours of straightening and machining afterwards. Some part shapes such as long shafts are best racked in vertical orientations to maintain straightness while other shapes such as rings are better if laid flat horizontally to maintain roundness. Selection and experience in designing heat treatment fixtures can dramatically affect the results. A third source of distortion is quenching, which is typically the main offender in distorting parts during heat treatment. The ideal quench is the slowest quench that will uniformly pull heat out of the part, while still fully transforming the surface to martensite and achieving the desired case and core properties. This sounds easy enough, but in practice it can be quite difficult given the design and complex shape of many gears. Due to variations in customers' part geometries, limitations in fixture designs, non-uniform quench tank agitation, and part-to-part or part-to-fixture interactions, it is the most difficult distortion mechanism to resolve and predict. Even within a single part it's possible to have some thinner sections of a component cool faster than thicker sections causing one area to transform earlier than another and warp dimensions as the transformations with their associated volume expansions occur at different times during a quench. When distortion occurs to an unacceptable degree, solutions need to be found. After exhausting all the variations of processing parameters, fixturing methods, quench modifications, and ensuring parts are free from stress prior to heat treatment, other options need to be considered. This can be as simple as a straightening step, or as difficult as re-engineering the part. Some other methods of heat treating include: Case Hardening Case hardening is a process of diffusing carbon into the surface of low carbon steel at elevated temperatures. This results in a high carbon case forming just inside the surface of a low carbon component. During quenching from austenitizing temperatures the austenite will transform to martensite, and the higher carbon case will have a high hardness while the lower carbon core material will have a lower hardness. The goal of this process is to produce a hard, strong, wear resistant outer surface while retaining a softer, ductile tough core. When austenite transforms to martensite during quenching, a volume expansion occurs in the material and it grows. The volumetric expansion in the case is greater than the volume expansion in the lower carbon, lower hardness core structure. This difference in size changes puts the carburized surface of the part into a state of compression, which makes it stronger. For example, when a force is applied to a gear tooth, it first has to overcome these compressive forces before beginning to put the surface of the tooth in tension. In order to deform this material, it requires a force that exceeds the combination of overcoming the compressive stresses present in addition to the normal yield strength of the material. These compressive stresses caused by differences in volume expansion rates between the case and core improves the overall tensile and yield strength of the carburized case inside a gear tooth. It is these compressive stresses that resist deformation from high contact stresses present as gear teeth press and roll against each other. These compressive stresses also increase fatigue life by helping to prevent cracking in tooth roots as the teeth are cyclically loaded and unloaded with bending stresses. The high carbon, high hardness surface of the carburized case also resists wear and scoring caused by friction as gear teeth rub and wear against each other. One can't discuss heat treating gears without discussing distortion, which occurs for a variety of reasons. One source is pre-existing residual stresses present in the material caused by prior operations such as steelmaking, rolling, forming, forging, casting, machining, and grinding. As the material begins to heat treat during carburizing, these residual stresses present in the material relieve and cause the gears to distort if these stresses were large or non-uniform. A secondary source of distortion is high temperature creep during processing. Gravity is the enemy of many gear designs during thermal processing, especially in carburizing, where high temperatures and long processing times are the norm. At high temperatures, steel has little strength and can sag and bend under gravity's force if sections of a part are not properly supported or components not stood up or hung perfectly straight. Spending the extra time to fixture parts correctly and designing customized fixtures to properly support a gear during exposure to high temperatures can save many hours of straightening and machining afterwards. Some part shapes such as long shafts are best racked in vertical orientations to maintain straightness while other shapes such as rings are better if laid flat horizontally to maintain roundness. Selection and experience in designing heat treatment fixtures can dramatically affect the results. A third source of distortion is quenching, which is typically the main offender in distorting parts during heat treatment. The ideal quench is the slowest quench that will uniformly pull heat out of the part, while still fully transforming the surface to martensite and achieving the desired case and core properties. This sounds easy enough, but in practice it can be quite difficult given the design and complex shape of many gears. Due to variations in customers